

2017 Student Housing Facilities Fire Safety System Report

Residential Facility	Fire Alarm Monitoring Done On Site (by security)	Partial ¹ Sprinkler System	Full ² Sprinkler System	Smoke Detection	Fire Extinguisher Devices	Evacuation Plans/ Placards	Number of evacuation (fire) drills each calendar year
Hyde Hall	Χ			Χ	X	Χ	3
Liston Hall	Χ			X	Χ	Χ	3
Lower Liston Hall	Χ			Χ	Χ	Χ	3
Liston Hall Suites	Χ			X	Χ	Χ	3
Mitchell Hall	Χ			Χ	Χ	Χ	3
Parks Hall	X			Χ	X	X	3

- 1. Partial Sprinkler System is defined as having sprinklers in the common areas only.
- 2. Full Sprinkler System is defined as having sprinklers in both the common areas and individual rooms.