



2019 Student Housing Facilities Fire Safety System Report

Residential Facility	Fire Alarm Monitoring Done On Site (by security)	Partial ¹ Sprinkler System	Full ² Sprinkler System	Smoke Detection	Fire Extinguisher Devices	Evacuation Plans/ Placards	Number of evacuation (fire) drills each calendar year
Hyde Hall	X			X	X	X	3
Liston Hall	X			X	X	X	3
Lower Liston Hall	X			X	X	X	3
Liston Hall Suites	X			X	X	X	3
Mitchell Hall	X			X	X	X	3
Parks Hall	X			X	X	X	3

1. Partial Sprinkler System is defined as having sprinklers in the common areas only.

2. Full Sprinkler System is defined as having sprinklers in both the common areas and individual rooms.